



BOAB Testverktyg

Byggmästargatan 9 Mellerud 46431 SE

Phone: 0530730793
EMail: erik@boabhjuldela.se
Web:

Customer:
Phone:
Email:

Vehicle scan summary

Date: 21/01/2023 14:44
Car plate: ABC123 Car model:


Front left

Brand: 
Size: /R
Season:
Speed rating: **Depth: 6,8**

6,2 7 7,3 6,5



Front right

Brand: 
Size: /R
Season:
Speed rating: **Depth: 7,0**

7,1 7,1 7 6,7



Rear left

Brand: 
Size: /R
Season:
Speed rating: **Depth: 5,5**


5,4 5,5 5,6 5,4







Rear right

Brand: 
Size: /R
Season:
Speed rating: **Depth: 7,1**

7,1 7,1 7,2 7,1



 Critical tire wear
 Irregular or uneven tire wear

 Warning wear
 Normal tire depth



BOAB Testverktyg

Byggmästargatan 9 Mellerud 46431 SE

Phone: 0530730793
EMail: erik@boabhjuldela.se
Web:


Customer:
Phone:
Email:

Vehicle scan summary

Date: 28/03/2022 11:20
Car plate: TEST2022 Car model:


Front left

Brand: 
Size: /R
Season:
Speed rating: **Depth: 4,4**




Front right

Brand: 
Size: /R
Season:
Speed rating: **Depth: 4,5**




Rear left



Brand: 
Size: /R
Season:
Speed rating: **Depth: 4,4**





Rear right

Brand: 
Size: /R
Season:
Speed rating: **Depth: 4,6**



 Critical tire wear
 Irregular or uneven tire wear

 Warning wear
 Normal tire depth